

| SER<br>-IAL | DRGS<br>DATE | PLAN<br>No. | DETAILS                                   | OCC'N      |
|-------------|--------------|-------------|-------------------------------------------|------------|
|             |              |             |                                           |            |
|             |              |             | PLATFORMS PROVIDED                        |            |
|             |              |             |                                           |            |
|             |              |             |                                           |            |
| 79          |              |             | UP G.R.L. ADV'D STARTING RECOVERED        | 22.3.1927  |
| 375         |              |             | TEMP. SIDING ON DOWN SIDE                 | 30.9.1928  |
| 379         |              |             | DOWN G.R.L. HOME RENEWED AS HALF BRACKET  | 8.10.1928  |
|             |              |             |                                           |            |
| 611         |              |             | DOWN MAIN INNER HOME RENEWED 8' OUT.      | 28.3.1929  |
|             |              |             |                                           |            |
| 983         |              |             | COKE SIDINGS ADDED                        | 22.11.1929 |
|             |              |             | UP ADV'D STARTING LOWERED BY 8FT 7T ADDED | 1.1.1930   |
| 1038        |              |             | DN HOME LOWERED BY 2FT                    | 2.1.1930   |
|             |              |             |                                           |            |
|             |              |             |                                           |            |

TRETHOMAS

RECORD OF AMENDMENTS

S 1370 /1/1

| SERIAL | DRGS DATE | PLAN No. | DETAILS                                                                                                     | OCC'N      |
|--------|-----------|----------|-------------------------------------------------------------------------------------------------------------|------------|
| 850    |           |          | 32 TRAP POINT RECOVERED                                                                                     | 10.8.1933  |
|        |           |          |                                                                                                             |            |
|        |           |          |                                                                                                             |            |
| A      | 3.52      |          | 29T & 35T PROVIDED 1/40 BARS                                                                                |            |
|        |           |          |                                                                                                             |            |
| B      | 8.55      |          | W.R. COMMUTATOR BLOCKS PROVIDED. BLOCK RELEASES ADDED                                                       |            |
| C      | 4.56      |          | SIGNALS 4, 9, 43 & 42/46 RENEWED                                                                            |            |
|        |           |          |                                                                                                             |            |
| D      | 8.56      |          | SIGNALS 47 & 49 RENEWED                                                                                     |            |
| E      | 8.60      |          | COLLIERY STARTING REPOSITIONED 5' NEARER S.B.                                                               |            |
| F      |           |          | UP ADV'D STARTING & LOWER DISTANT RECOVERED. CLOSURE OF BEDWAS COLLY NORTH S.B. - SECTION WORKED AS SIDINGS | 17.12.1963 |
|        |           |          |                                                                                                             |            |

TRETHOMAS

RECORD OF AMENDMENTS

S 1370/1/2