


ER




21. Lever Frame

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	
	1.	6 5 4				8		8	11		11	14 07 14 16		14	14	14					18 19 20

W 21. (989) ER

PREESGWEEENE 1926



POINTS 34 and 37
are worked by electric motors