

SERIAL	DWGS DATE	PLAN No.	DETAILS	OCC'N
			28T PROVIDED	7.1961
			WREXHAM SOUTH	
			RECORD OF AMENDMENTS	S /1

WREXHAM SOUTH — very rough R.O.A.

- TC in back platform & CO arm 64 into use
- TCs in up bay lines into use.
- ? → TC in rear of VMS into use
- Two TCs on DM into use
- C.O. arms 40 & 60 into use
- No 2 bay line converted to siding & cars to Nol bay fou.
- Facing DM → bays t.o.u. (Notice No. 21)
- SIGNAL 57/59 RENEWED AS LH BRACKET. ----- 6.6.43
- TCs 26T & 27T into use, holding FPL levers levers.
- FPL 26A becomes 27B, lifting bars removed (Notice No 140)
- Signal 5/18/19 renewed with elevated discs.
- Ⓣ Levers 15, 16, 17 ton [etc etc.]
- CO arm provided for DM as well as for Back Plat (64 selected)
- Signal 68/66 renewed as RH bracket DMH only. 66 space.
- SB abolished (plan C5 68/66)

BY 1919.

} BY 1919?

1919/24.

1924/37

} 17-21.1.37

6.6.43

} 20-24.3.1960.

1960/62.

} N/K.
BY 1960

1968